## REPORT

## TRUESDAIL LABORATORIES, INC.

HEMISTS - MICROBIOLOGISTS - ENGINEERS

RESEARCH

DEVELOPMENT

Douglas Aircraft Company CLIENT

Internal Mail Code 211-40

3855 Lakewood Blvd.

Long Beach, CA 90846

Attn: Robert M. Tomko SAMPLE

Storm drain inspection - 2 quarter

P.O.#T & M 23465 C

INVESTIGATION



14201 FRANKLIN AVENUE TUSTIN, CALIFORNIA 92680 AREA CODE 714 . 730-6239 AREA CODE 213 . 225-1564 CABLE: TRUELABS

June 15, 1988

RECEIVED May 31, 1988

LABORATOR**2**6666/26667

As requested by the CRWQCB for MPDES permit #'s CA0001406 & CA0001414

## RESULTS

A representative of Truesdail Laboratories, Inc., tested the storm drain discharge on May 31, 1988, at the Douglas, Torrance facility and Long Beach facility (003). The discharge was tested for flow rate, pH, and temperature. A grab sample was returned to the laboratory's and analyzed according to the American Public Health Association's "Standard Methods," 16th Edition. The results are as follows:

Sample I.D.	<u>Date</u>	<u>Time</u>	Flow - gpd	Temp OF	pH Units
(กกัง) 💮	5/31/88	3:20	134,525	75	7.9
Torrance	5/31/88	2:00	meter out servi	ce 74	7.8

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from these Laboratories.